NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER



25X1

basic imagery interpretation report

Radar Cross-Section
Test Facilities, USSR (S)

COMMO/ELEC/RADAR R&D FACILITIES BE: Various USSR



Secret

WNINTEL

Z-14639/82 RCA-20/0001/82 DECEMBER 1982 Copy 1 Q



INSTALLATION OR ACTIV						25X
Radar Cross Soct	ITY NAME				COUNTRY	
Radar Cross-Section Test Facilities					UR	
UTM COORDINATES	GEOGRAPHIC COORDINATES	CATEGORY	BE NO.	COMIREX NO.	NIETB NO.	
NA	See below	See belov	See below	See below	See below	
MAP REFERENCE	•				-l	
SAC. USATC, Ser	ies 200, Various sheets, scal	e 1:200,000				
LATEST IMAGERY USED		NEGA	NEGATION DATE (If required)			
See Abstract		NA NA				
		ABSTRAC	T			
capable of suppor	ive Soviet radar research each of the five facilities ting test vehicles/objects of	is a radar cro on a cable stru	oss-section test ing between the	area with two em.	or more towers	
30 September 198.	his report describes the fiv 2. Included are a location r	e facilities and nap and eight	d the activity at a annotated pho	each from Janu tographs.	ary 1970 through	
	IN	ITRODUCT	ION			
section test areas. Kalinin and Volok	d development/test faciliticts suspended from a wire In addition, rotatable plat olamsk. All applicable imagreparation of this report,	e strung betw forms for rada gerv acquired	een the towers ar cross-section from lanuary 1	are at each of tests are at two 970 through	the radar cross- of the facilities,	25X
	BAS	IC DESCRIF	PTION			
Aralsk Research	n and Development Tr					
4 40 44 11 11		oposcatter a	and Radcom	Receiver Stat	ion	
tation consists of	ralsk Research and Develop Station is 13 nautical miles a radar cross-section test an nications area (Figure 3).	oment Tropos (nm) west of	catter and Radio	o Communicati	ons (R&D Tropo	
tation consists of ation and commu  5. (S/WN) The acters apart with a uspended between the acters apart with tress insulators apart inch house next apped structures, and may be used	Station is 13 nautical miles a radar cross-section test a nications area (Figure 3). The radar cross-section test at a rectangular concrete pen the towers four times she towers, it hung in a paraproximately 65 meters inbot o each of the towers. Equal with the top of each flush as camera positions. A sm	oment Tropos (nm) west of rea (Figure 2), area consists of pad centered ince 1970, the abola with its pard of the to pally spaced ar with the grou	catter and Radic Aralsk, on the ran operations so of two guyed 170 between theme latest in July low point over twers. The heigh ound the rectaind. These structed huilding 538	o Communication or the shore of the upport area, and other or the shore of the cable is the cable is neutres have small or the cable is neutres and the cabl	ons (R&D Tropo he Aral Sea. The d an instrumen- ttice towers, 700 been observed e cable was sus- d. The cable has controlled by a pad are four L-	
sadcom) Receiver tation consists of ation and commu 5. (S/WN) The teters apart with uspended between the tress insulators applied in the tress insulators applied in the tress, and may be used ad, is connected 6. (S/WN) Lieriod. The last a	Station is 13 nautical miles a radar cross-section test a nications area (Figure 3). The radar cross-section test at a rectangular concrete pen the towers four times she towers, it hung in a paraproximately 65 meters inbot to each of the towers. Equivith the top of each flush	oment Tropos (nm) west of rea (Figure 2), area consists of pad centered ince 1970, the abola with its pard of the to ally spaced ar with the grou all unidentified cable to the r	catter and Radic Aralsk, on the ran operations so of two guyed 170 between theme latest in July 1 low point over twers. The heigh ound the rectaind. These structed building, 535 ectangular conc	o Communication or the shore of tupport area, and one ter-high land a cable has 1979. When the concrete pattof the cable is negular concrete tures have smale meters norther tere pad.	ons (R&D Tropo he Aral Sea. The d an instrumen- ttice towers, 700 been observed cable was sus- d. The cable has controlled by a pad are four L- l hatches on top of the concrete	25X
adcom) Receiver tation consists of ation and commu  5. (S/WN) The term apart with uspended between the tress insulators apprinch house next maped structures, and may be used ad, is connected  6. (S/WN) Liferiod. The last apprince to pad.  7. (S/WN) The cotion), a four-bayocket forces obsthen several trans	station is 13 nautical miles a radar cross-section test a nications area (Figure 3). The radar cross-section test a a rectangular concrete pen the towers four times she towers, it hung in a paraproximately 65 meters inbot to each of the towers. Equivith the top of each flush as camera positions. A sm by road and underground ttle activity was observed	ment Tropos (nm) west of rea (Figure 2), area consists of the to ally spaced are with the grou all unidentificable to the rat the radar april 1971, when the space of the totally spaced are with the group all unidentificable to the rat the radar april 1971, when the space of the two barracks, as been observances are works with two barracks, as been observances are works with the search of the two barracks, as been observances are works with the search of the two barracks, as been observances are works with the search of the two barracks, as the search of the two barracks.	catter and Radic Aralsk, on the ran operations so of two guyed 170 between theme a latest in July 160 low point over twers. The heigh ound the rectaind. These structed building, 535 ectangular conc cross-section them a hree checkout lasteam plant, reed in the sun	Decommunication of the shore of the concrete part of the cable is meters have small meters north area during diameter objects of the cable is meters north area during diameter objects of the cable is meters of the cable is meters.	ons (R&D Tropo he Aral Sea. The d an instrumentice towers, 700 been observed e cable was susd. The cable has controlled by a pad are four L-l hatches on top of the concrete get he reporting ect was on the with a high-bay, and a strategic the mid 1970s	25X
adicom) Receiver tation consists of ation and commu  5. (S/WN) The ters apart with uspended between tended between tress insulators apprinch house next naped structures, and may be used ad, is connected  6. (S/WN) Lieriod. The last appropriate pad.  7. (S/WN) The concrete pad.  7. (S/WN) The concrete pad.  8. (S/WN) The concrete pad.  9. (S/WN) The concrete pad.  10. (S/WN) The concrete pad.  11. (S/WN) The concrete pad.  12. (S/WN) The concrete pad.  13. (S/WN) The concrete pad.  14. (S/WN) The concrete pad.  15. (S/WN) The concrete pad.  16. (S/WN) The concrete pad.  17. (S/WN) The concrete pad.  18. (S	Station is 13 nautical miles a radar cross-section test an inications area (Figure 3). The radar cross-section test at a rectangular concrete pen the towers four times she towers, it hung in a parsiproximately 65 meters inbot to each of the towers. Equivity the top of each flush as camera positions. A sm by road and underground ttle activity was observed in A tectivity was observed in A tect	oment Tropose (nm) west of rea (Figure 2), area consists of add centered ince 1970, the boald with the spaced are with the grouall unidentificable to the rat the radar april 1971, who consists of the two barracks, as been observed by the two eastern to a DISH tropo EEL telemetry the two eastern an azimuth	catter and Radic Aralsk, on the ran operations so of two guyed 170 between theme latest in July 100 low point over twers. The heigh ound the rectaind. These structed building, 535 ectangular concerns-section to a steam plant, rved in the suph probable versame area is on a blumentation portantennas, orientations, oriental conference of 225 degrees	o Communication orth shore of to upport area, and on the cable has 1979. When the concrete pat of the cable is neuters have small of meters north trete pad.  The cable has 1979 area during diameter object of the cable is neters north trete pad.  The cable has 1979 area during diameter object area during plant port area since it is support ring for orthing the cable of the cable o	ons (R&D Tropo he Aral Sea. The d an instrumentice towers, 700 been observed e cable was susd. The cable has controlled by a pad are four Lhatches on top of the concrete g the reporting ect was on the with a high-bay, and a strategic the mid-1970s, and a strategic the radar crossconsists of four ars, and a SHIP he radar cross-l buildings. The payler concrete	25X
sadcom) Receiver tation consists of ation and commu  5. (S/WN) The ters apart with uspended between tended between teres insulators applied by the condition of the last appearance of the last applied forces obstituted forces obs	Station is 13 nautical miles a radar cross-section test an inications area (Figure 3). The radar cross-section test as a rectangular concrete pen the towers four times she towers, it hung in a paraproximately 65 meters inboto each of the towers. Equivity the top of each flush as camera positions. A smby road and underground title activity was observed in A processes of the course observed in A protectivity was observed in A protectivity was observed in A protectivity of the high-bay checkout e instrumentation and come the operations support a patrol buildings, two TWIN ation site. Two SHIP WH ere on the roof of each of opo antennas, oriented or	oment Tropose (nm) west of rea (Figure 2), area consists of add centered ince 1970, the boald with the spaced are with the grouall unidentificable to the rat the radar april 1971, who consists of the two barracks, as been observed by the two eastern to a DISH tropo EEL telemetry the two eastern an azimuth	catter and Radic Aralsk, on the ran operations so of two guyed 170 between theme latest in July 100 low point over twers. The heigh ound the rectaind. These structed building, 535 ectangular concerns-section to a steam plant, rved in the suph probable versame area is on a blumentation portantennas, orientations, oriental conference of 225 degrees	o Communication orth shore of to upport area, and on the cable has 1979. When the concrete pat of the cable is neuters have small of meters north trete pad.  The cable has 1979 area during diameter object of the cable is neters north trete pad.  The cable has 1979 area during diameter object area during plant port area since it is support ring for orthing the cable of the cable o	ons (R&D Tropo he Aral Sea. The d an instrumentice towers, 700 been observed e cable was susd. The cable has controlled by a pad are four Lhatches on top of the concrete g the reporting ect was on the with a high-bay, and a strategic the mid-1970s, and a strategic the radar crossconsists of four ars, and a SHIP he radar cross-l buildings. The payler concrete	25X




FIGURE 1. LOCATIONS OF FIVE RADAR R&D FACILITIES, USSR

Installation	BE No	Geographic Coordinates	NIETB No
Aralsk R and D Tropo Radcom Receiver Station		46-46-17N 061-20-48E	
Belousovo Probable Electronics Test/Trng Facility		55-04-30N 036-42-00E	
Kalinin Radar Test Facility		56-53-07N 035-56-22E	
Ulyanovsk Radar Calibration/ Checkout Facility		54-24-20N 048-19-06E	
Volokolamsk Radar R and D Facility		56-01-10N 036-07-30E	

ing. The two FLAT FACE radars, adjacent to the TWIN DISH antennas, are also oriented on an azimuth of 225 degrees. On several coverages during the reporting period, one of the FLAT FACE radars was observed with the antenna sails rotated vertically rather than horizontally. A long clutter screen, with sections in various stages of elevation, was along the edge of the bluff between the antennas and the radar cross-section test area. The SHIP WHEEL instrumentation site is just north of the instrumentation/control buildings and consists of two van-mounted SHIP WHEEL antennas and three support vans. The SHIP WHEEL antennas are cable connected to the western instrumentation/control building.

9. (S/WN) The separately secured communications facility is to the east and across the road from the instrumentation area. This facility consists of one control building, two horizontal dipole antennas, one 2-2-2 fishbone antenna, and one antenna mast. The horizontal dipoles are oriented on azimuths of the fishbone antenna is oriented on an azimuth of 105/285 degrees.


### **Belousovo Probable Electronics Test/Training Facility**

- 10. (S/WN) The Belousovo Probable Electronics Test/Training Facility is 3.5 nm southeast of Obninsk and is involved in radar cross-section testing, the probable testing of airborne platforms, and other unidentified testing. The facility consists of a radar cross-section test area, three other test areas, an equipment storage area, an unidentified area, and two housing/support areas (Figure 4).
- 11. (S/WN) The radar cross-section test area, in the eastern corner of the facility, consists of two 45-meter-high towers, 158 meters apart and with an oval concrete pad centered between them. A concrete test position with a control building and two support buildings is immediately south of the concrete pad. A second concrete test position is approximately 300 meters south of the test area. No activity has been observed on the closest concrete pad, but an unidentified van has been observed on the second.

25X1

25X1

Z-14639/82 - 2 - RCA-20/0001/82




- 12. (S/WN) The three other test areas are in a semicircle around the radar cross-section test area. The northernmost test area is separately secured and consists of a concrete pad, an unidentified tower, and a control building. During the reporting period, the tower was observed cable connected to a large unidentified vehicle parked on the concrete pad. The central test area consists of four concrete pads and a probable calibration pad. Once during the reporting period, HIP helicopters were observed on one of these concrete pads, indicating that airborne platforms were tested in this area. The southernmost test area consists of two concrete pads, a secured calibration area, and a probable calibration pad.
- 13. (S/WN) The unidentified area is secured by a rectangular fence and consists of one building with an antenna pedestal on the roof and an unoccupied concrete pad.
- 14. (S/WN) The equipment storage area is secured and in the center of the facility. This area consists of one building and two concrete pads. Two van-mounted SHIP WHEEL antennas, four support vans, and an unidentified air traffic control radar were observed within this area during the reporting period.
- 15. (S/WN) The housing/support areas consist of one high-bay building, one shop building, three vehicle maintenance buildings, and 14 housing/support buildings.

### **Kalinin Radar Test Facility**

- 16. (S/WN) The Kalinin Radar Test Facility, 2.0 nm northeast of Kalinin, is involved in radar cross-section testing, using both suspension test towers and rotatable test platforms. TALL KING and SQUARE PAIR radars were observed undergoing testing during the reporting period; however, in the past, BAR LOCK, FAN SONG, FLAT FACE, STONE CAKE, and SPOON REST radars have undergone testing there. Other electronics equipment there, probably used in the checkout and calibration of radars, includes TALL RODS high-frequency/direction-finding (HF/DF) equipment, TUB BRICK radar jammers, and SHIP WHEEL telemetry antennas.
- 17. (S/WN) When last observed, on \_\_\_\_\_\_\_\_one FISHBED, one FRESCO, and two unidentified airframes were at the test facility probably being used for radar cross-section testing or possibly for airborne radar calibration. In the past several years, the aircraft and airframes identified at Kalinin have included the FOXBAT, FLOGGER, FARMER, a canvas-covered probable scale model of the CHARGER SST, and probable LA-17 drones. Also, SA-1, probable AS-6, and possible AS-9 missiles have been observed there.
- 18. (S/WN) Kalinin Radar Test Facility consists of a radar cross-section/test area, a radar test line, two fishbone antennas, four horizontal dipole antennas, and a housing/support area (Figure 5).
- 19. (S/WN) The radar cross-section/test area consists of three lattice towers in an L-shaped arrangement. This L-shaped arrangement is generally oriented north/south and east/west. The two towers on the east/west leg, 75 meters high, are approximately 200 meters apart. The towers on the north/south leg, 75 meters and 65 meters high, are approximately 200 meters apart. At different times during the reporting period, airframes were observed next to the towers, but none of the airframes were observed suspended between the towers. Rotatable test platforms, between the towers on both legs of the L-shaped arrangement, are used to rotate objects, thus providing different aspect angles to the radars. No equipment was observed on these platforms during the reporting period.
- 20. (S/WN) The radar test line, along the western edge of the facility, is divided into five test areas designated A through E. Test area A, the southernmost area, consists of a concrete hardstand, an earthern pad, and two control/test buildings. Five clutter screens were observed between test area A and the radar cross-section/test area. During the reporting period, a TALL KING radar and SQUARE PAIR radar components were being tested in area A. Test area B consists of a circular concrete pad, surrounded by a board or canvas screen, two test control buildings, and a wall-secured equipment storage yard. Since at least 1975, a SQUARE PAIR radar has been on the circular concrete pad, and related electronics vans are cable connected to one of the test/control buildings. Test area C consists of a graded-earth test area, one test/control building, and two support buildings. No radars have ever been identified at test area C; however, during the reporting period, electronics vans were observed undergoing testing there. Test area D consists of a concrete pad, a graded-earth pad, a test/control building, a secured vehicle storage area, a vehicle storage building, and two support buildings. Only electronic countermeasures equipment is present. However, in the past, BAR LOCK and SIDE NET radars were tested there. Test area E consists of a graded-earth test position, a concrete hardstand, a test/control building, a secured equipment storage area, and one support building. For the past several years, a TALL KING C radar and a SCORE BOARD identification friend or foe have been on the concrete pad. During the reporting period, the support vans for the TALL KING were observed on the concrete pad and within this pentagonal area, formed by the four horizontal dipole antennas. A TALL RODS HF/DF antenna was observed on a hill behind the secured equipment storage area.
- 21. (S/WN) The housing/support area, behind the radar test line along the west edge of the facility, consists of a barracks area, a secured motor pool, a secured fuel storage area, and two equipment storage yards. The barracks area includes four barracks, one messhall, a security building, three support buildings, an athletic field, and an obstacle course. The secured motor pool consists of one vehicle maintenance building and three vehicle storage buildings. The secured fuel storage area contains two POL storage bunkers, two storage buildings, and three support buildings. The two equipment storage yards are secured areas, each with a small storage building.

25X1



#### Sanitized Copy Approved for Release 2010/03/25 : CIA-RDP83T00574R000103040001-8 SECRET

#### Ulyanovsk Radar Calibration/Checkout Facility

22. (S/WN) The Ulyanovsk Radar Calibration/Checkout Facility, 5 nm north-northwest of Ulyanovsk, is involved in the testing/calibration of a new probably vehicle-mounted radar system, as indicated by the presence of a special-purpose trailer in test area B on This special-purpose trailer has been used in the past to conceal military vehicles during transit from production plants to test facilities.

was the first time this vehicle was seen at this facility. On this date, all of the root panels had been removed from the trailer, but the end sections were still in place. In addition to the special-purpose trailer, a computer van, two support vans, and a box-bodied van were also observed on that date.

23. (S/WN) Ulyanovsk radar facility consists of two separately secured radar test areas—designated A and B—a radar cross-section test area, and four calibration towers (Figure 6). Test area A is wall secured and consists of a test control building with four large doors and a high-bay section. Four test stands and three small calibration towers are in front of the test control building. During the reporting period, two of the four test stands which have always been observed occupied by probable signal generator vans were cable connected to the test control building.

24. (S/WN) Test area B, fence secured, consists of one test/control building with two large doors and a test stand. During the reporting period, the special-purpose trailer and the four vans were observed next to the test/control building.

25. (S/WN) The radar cross-section test area consists of two towers that are 32 meters high and 75 meters apart. A spherical radar target is suspended 30 meters aboveground, midway between the towers. The position of the target has never been changed since it was first observed in early 1974.

26. (5/WN) Four test/calibration towers, designated 1 through 4, are at the Ulyanovsk radar facility. Small structures are atop all four of these towers. Tower 1 is 22 meters high, and tower 2 is 32 meters high; both are cable connected to the test/control building in area B. Towers 3 and 4 are both 32 meters high and are probably cable connected to the test control building in area A.

#### Volokolamsk Radar R&D Facility

27. (S/WN) The Volokolamsk Radar R&D Facility, 5.5 nm east of Volokolamsk, is involved in radar cross-section testing and in air-warning and air traffic control radar testing. This facility (Figure 7) consists of six test areas, designated A through F, and an administration/general support area.

28. (S/WN) Test area A, the radar cross-section test area, is in the northeast corner of the facility. This area consists of three 40-meter-high lattice towers, with a cable strung between two of them (Figure 8). The third tower is equidistant from the other two towers and forms a triangle; however, the third tower is not cable connected to the other two towers. A concrete pad with a rotatable test platform was observed centered between the two cable-connected towers. On the south side of the concrete pad is an a-frame crane that can be raised over the concrete pad to lift objects on and off the rotatable test platform. This crane has always been observed in a lowered position. Various unidentified pieces of equipment have been observed on the concrete pad. A second concrete pad for static testing of equipment is northeast of the first concrete pad. During 1979, an SA-2 launcher was on the static concrete pad. During 1979, an SA-2 launcher was on the static concrete pad. During 1980, an SBN-4N navigational aid was on the second concrete pad. Support for area A includes three test buildings, a control building, two support buildings, and several electronics vans.

29. (5/WN) Test area B is unsecured and in the north-central portion of the facility and consists of three radar mounds occupied by one BAR LOCK radar, one SIDE NET radar, and one FLAT FACE A radar. Other electronics equipment around area B includes one SQUAT EYE radar, one SPOON REST radar, three tower-mounted CONE DISH antennas, and one MERCURY PLATE antenna system. Support for area B includes one double arch-roofed bunker in the late stage of construction, three shop buildings, a radar storage building, six support buildings, and two water towers.

30. (S/WN) Test area C is secured and in the northwest corner of the facility and consists of two test positions and a control building. During the reporting period, no activity was observed in area C.

31. (S/WN) Test area D is secured and on the west side of the facility and consists of one multibay test building, one small test building, a calibration tower, and three small support buildings. A probable navigational aid was observed in this area in front of the multibay test building during 1981.

33. (S/WN) Test area F (Figure 9) is on the southern edge of the facility and consists of six small test buildings, each with a calibration tower or a calibration position, a water tower, and five support buildings. Several small dish antennas and a van trailer were observed in this area during the reporting period.


34. (S/WN) Housing/support for the facility is in the center of the installation and consists of one administration building, six multistory barracks, two probable quarters, a heating plant, a vehicle maintenance building, and several support buildings.

25X1

25X1 25X1

25X1

Z-14639/82 - 8 - SECRET



## Sanitized Copy Approved for Release 2010/03/25 : CIA-RDP83T00574R000103040001-8 SECRET

IMAGERY		
(S/WN) All available satellite imagery acquired from January 1970 to union of this report.	vas used in the prepara-	25X1
MAPS OR CHARTS		
SAC. US Air Target Chart, Series 200, Various Sheets, scale 1:200,000 (UNCLASSIFIED)		
REQUIREMENT		
COMIREX U01 Project 542065U		
(S) Comments and queries regarding this report are welcome. They may be directed Soviet Strategic Forces Division, Imagery Exploitation Group, NPIC,	to	25 <b>X</b> 1 25 <b>X</b> 1

REFERENCES

# **Secret**

# **Secret**